

FIG. 3






FIG. 4






FIG. 5







FIG. 6







1330.1085





FIG. 8










FIG. 10






FIG. 11



SELECT POWER PLANT 400 -LOG INTO ADCS DISPOSITION OBJECT SELECT POWER PLANT OBJECT FOR INSPECTION OPEN LOGSET SCREEN **REVIEW RECORD** 408 406 410 DATA ACCURATE NO RECORD ACCURATE INFORMATION YES RECORD INSPECTORS ID NUMBER ON RECORD 414 416 ALL RECORDS COMPLETE NO YES **CLOSE LOGSET** 418 -SCREEN **END**

FIG. 12



434 432 -SELECT POWER PLANT SELECT POWER PLANT DISPOSITION OBJECT LOG INTO ADCS OBJECT FOR INSPECTION 438 436 OPEN ENGINEERING DOCUMENT SCREEN REVIEW RECORD 440 442 -DATA ACCURATE NO RECORD ACCURATE INFORMATION YES RECORD INSPECTORS ID NUMBER ON RECORD 446 ALL RECORDS COMPLETE CLOSE ENGINEERING DOCUMENT SCREEN NO YES 450 -END

FIG. 13



